5 of the Work Order. MARKINGS: Per paragraph 6 of the Work Order.

ADDITIONAL INSTRUCTIONS

If asterisk (*) is indicated beside the item, Air Shipment is authorized. Overtime premium time in the amount of none is authorized.

> SECRET (WHEN FILLED IN) **Declass Review by NIMA/DOD**

PAGE 4 OF 32 MORS

MOLE.		DWG. HR.	OWNER
15		2-127	1
16		2-128	ī
17	* - #	2-129	Ī
18		2-130	•
19		2-131	12
20		2-114	1
21		2-137	1
22		2-1-5	2
23		2-139	2.1
24		3-140	1
25		2-141	\mathbf{i}
26		2-142	i
27		2-143	6
26	A Company	2-144	
29	من 	2-145	
30		2-146	
31	**	2-147	
32		2-149	

2. The Contractor will provide the following seditional hardwore items in the quantities shows:

TIM			GENERALLY
Valdes #5008-100 Smap Ringe			10 each
Weldes #5008-175 Snap Rings			4 each
Enurled Bress Screws, \$10-32	x 3/4 long Bickel Plat	ed .	100 etch
Knurled Brass Screws, 1/4	20 z 1" long Hickel Fl	sted	100 esch
5/16 die. x 3/8 long shoulds finish	or serews, 1/4-20 thd.,	plein	10 each
All thread rod \$10-32 x 36,	steel, cod. plate (tota	1)	h each
All thread rod $1/4-20 \times 36$ ",	steel cod. plete (tote	1	4 cech
All thread rod 3/8-16 x 36,	steel end. plate (tota	1)	4 etch